



MECHANICAL EMISSIONS SERVICES LLC
 300 W Cole Rd, Suite 5C
 Calexico, CA 92231
 (619) 845-1299



Cert Number

VIN


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3N1CN7APXKL843828	Year	2019		
Mfg In	MEXICO	Make	Nissan	Owner's Name	LA LLAVE IMPORTS S.A DE C.V
Model	Versa	License Plate	22 NONE	Odometer (mi)	85181 137085.19054 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEC2-00000594	Geo Location	Latitude: 32.693726, Longitude: -115.504535
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	06 David Early	Inspector Signature	<i>David Early</i>
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20241220915710	Date	2024/12/26 Expires: 2025/03/26



Sernarat Authorization Letter
 No. SRA.600/DPRA/DPMR/377/2022
 CA BAR 97 GEN3 and/or Drew Technologies IMClean
 ESP 10400-89 Software Version: 16028007727838
 To verify this Certificate please go to:
www.mecemissions.com

