



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3N1CP5CU8JL542412		Year	2018	
Mfg In	MEXICO	Make	Nissan	Owner's Name	JOSE LUIS MEDINA CARRILLO
Model	Kicks	License Plate	K4	Odometer (mi)	130263 209637.45642 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEC2-00004142	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	05 Lorena Valdez	Inspector Signature	Lorena Valdez
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260123542412	Date	2026/01/23 Expires: 2026/04/23



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

