



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	1V2DR2CA2JC503843		Year	2018	
Mfg In	UNITED STATES	Make	Volkswagen	Owner's Name	JOSE LUIS MEDINA CARRILLO
Model	Atlas	License Plate	K4	Odometer (mi)	115961 186620.67574 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEC2-00004143	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	05 Lorena Valdez	Inspector Signature	Lorena Valdez
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260123503843	Date	2026/01/23 Expires: 2026/04/23



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

