



VIN

**MECHANICAL EMISSIONS SERVICES LLC**  
22 East 7th Street  
Calexico, CA 92231  
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	2HGFC2F89LH553404		Year	2020	
Mfg In	CANADA	Make	Honda	Owner's Name	MARIA GUADALUPE PEREZ BARRON
Model	Civic	License Plate	C4	Odometer (mi)	26095 41995.72730 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEC9-00001329	Geo Location	Latitude: 32.671667, Longitude: -115.497500
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	09 Alexis Mosqueda	Inspector Signature	<i>Alexis Mosqueda</i>
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260120203018	Date	2026/01/23 Expires: 2026/04/23



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMP/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

