



VIN

MECHANICAL EMISSIONS SERVICES LLC
22 East 7th Street
Calexico, CA 92231
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5FPYK2F59HB008369		Year	2017	
Mfg In	UNITED STATES	Make	Honda	Owner's Name	S DE RL DE CV ERIK AUTOMOTRIZ LOZANO CAAAREM PAGADO
Model	Ridgeline	License Plate	C4	Odometer (mi)	188030 302604.20020 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEC9-00002566	Geo Location	Latitude: 32.671667, Longitude: -115.497500
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	09 Alexis Mosqueda	Inspector Signature	Alexis Mosqueda
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260825782610	Date	2026/08/28 Expires: 2026/11/28



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMP/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

