



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5NPD84LF9HH113557		Year	2017	
Mfg In	UNITED STATES	Make	Hyundai	Owner's Name	IMC AUTO IMPORTACION SA DE CV
Model	Elantra	License Plate	61 NONE	Odometer (mi)	97659 157166.53506 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN2-00002932	Geo Location	Latitude: 31.364765, Longitude: -110.957118	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	72 Francisco Leyva	Inspector Signature	Francisco Leyva	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20250603801070	Date	2025/06/17	Expires: 2025/09/17



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

