



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5XXGT4L32GG082504		Year	2016	
Mfg In	UNITED STATES	Make	Kia	Owner's Name	IMC AUTO IMPORTACION SA DE CV
Model	Optima	License Plate	61 NONE	Odometer (mi)	132032 212484.37888 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN2-00003870	Geo Location	Latitude: 31.364765, Longitude: -110.957118	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	72 Francisco Leyva	Inspector Signature	Francisco Leyva	
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20250814746710	Date	2025/08/15	Expires: 2025/11/15



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

