



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	1GCNCNEH0HZ130294		Year	2017	
Mfg In	UNITED STATES	Make	Chevrolet	Owner's Name	VALCA CAR SALES
Model	Silverado 1500	License Plate	61 NONE	Odometer (mi)	101441 163253.05894 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN2-00003877	Geo Location	Latitude: 31.364765, Longitude: -110.957118	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	72 Francisco Leyva	Inspector Signature	Francisco Leyva	
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20250814742115	Date	2025/08/16	Expires: 2025/11/16



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

