



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	2HGFC1F77HH641053		Year	2017	
Mfg In	CANADA	Make	Honda	Owner's Name	VALCA CAR SALES
Model	Civic	License Plate	61 NONE	Odometer (mi)	96908 155957.92072 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN2-00003879	Geo Location	Latitude: 31.364765, Longitude: -110.957118
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	72 Francisco Leyva	Inspector Signature	Francisco Leyva
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20250811557000	Date	2025/08/16 Expires: 2025/11/16



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

