



VIN

MECHANICAL EMISSIONS SERVICES LLC  
1270 W. Mariposa Ranch Road  
Nogales, AZ 85621  
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	2HGFC1F77GH636403		Year	2016	
Mfg In	CANADA	Make	Honda	Owner's Name	VALCA CAR SALES
Model	Civic	License Plate	61 NONE	Odometer (mi)	130541 210084.85294 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN2-00003880	Geo Location	Latitude: 31.364765, Longitude: -110.957118	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	72 Francisco Leyva	Inspector Signature	Francisco Leyva	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20250805216687	Date	2025/08/16	Expires: 2025/11/16



Sernarat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

