



VIN

MECHANICAL EMISSIONS SERVICES LLC  
1270 W. Mariposa Ranch Road  
Nogales, AZ 85621  
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	1FM5K8GT6GGD14196		Year	2016	
Mfg In	UNITED STATES	Make	Ford	Owner's Name	IMPORTAUTOS GI S.A. DE C.V.
Model	Explorer	License Plate	61 NONE	Odometer (mi)	119283 191966.90322 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN2-00003882	Geo Location	Latitude: 31.364765, Longitude: -110.957118
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	72 Francisco Leyva	Inspector Signature	Francisco Leyva
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20250816874138	Date	2025/08/16 Expires: 2025/11/16



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

