



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3FADP4BJ8GM122158		Year	2016	
Mfg In	MEXICO	Make	Ford	Owner's Name	VALCA CAR SALES
Model	Fiesta	License Plate	61 NONE	Odometer (mi)	116299 187164.63266 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN2-00005009	Geo Location	Latitude: 31.364765, Longitude: -110.957118	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	72 Francisco Leyva	Inspector Signature	Francisco Leyva	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20251013977143	Date	2025/10/18	Expires: 2026/01/18



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

