



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3N1CN8DV2LL918667		Year	2020	
Mfg In	MEXICO	Make	Nissan	Owner's Name	JOSE ALFREDO REYES ESQUIVEL
Model	Versa	License Plate	84 NONE	Odometer (mi)	63394 102022.49996 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN3-00000431	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	77 Gabriela Alvarez	Inspector Signature	Gabriela Alvarez
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20241220908350	Date	2024/12/26 Expires: 2025/03/26



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

