



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number



Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5N1AT2MV8HC863003		Year	2017	
Mfg In	UNITED STATES	Make	Nissan	Owner's Name	JANETTE ALVIDREZ MERAZ
Model	Rogue	License Plate	84 NONE	Odometer (mi)	160244 257887.07896 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN3-00015831	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	77 Gabriela Alvarez	Inspector Signature	Gabriela Alvarez
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260714305082	Date	2026/07/15 Expires: 2026/10/15



Sernat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

