



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3KPC24A30JE029479		Year	2018	
Mfg In	MEXICO	Make	Hyundai	Owner's Name	JANETTE ALVIDREZ MERAZ
Model	Accent	License Plate	84 NONE	Odometer (mi)	112125 180447.24750 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN3-00015832	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	77 Gabriela Alvarez	Inspector Signature	Gabriela Alvarez
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260714309717	Date	2026/07/15 Expires: 2026/10/15



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

