



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number



Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	1GT42VCG9JF172043		Year	2018	
Mfg In	UNITED STATES	Make	GMC	Owner's Name	JANETTE ALVIDREZ MERAZ
Model	Sierra 3500HD	License Plate	84 NONE	Odometer (mi)	186522 300177.31548 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN3-00015834	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	77 Gabriela Alvarez	Inspector Signature	Gabriela Alvarez
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260710172626	Date	2026/07/15 Expires: 2026/10/15



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

