



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5NPE34AFXHH590858		Year	2017	
Mfg In	UNITED STATES	Make	Hyundai	Owner's Name	JANETTE ALVIDREZ MERAZ
Model	Sonata	License Plate	84 NONE	Odometer (mi)	103686 166866.02724 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN3-00015836	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	77 Gabriela Alvarez	Inspector Signature	Gabriela Alvarez
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260714340400	Date	2026/07/15 Expires: 2026/10/15



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

