



VIN

MECHANICAL EMISSIONS SERVICES LLC  
1270 W. Mariposa Ranch Road  
Nogales, AZ 85621  
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

|        |                   |               |            |               |                               |
|--------|-------------------|---------------|------------|---------------|-------------------------------|
| VIN    | 1V2CR2CA9JC567891 |               | Year       | 2018          |                               |
| Mfg In | UNITED STATES     | Make          | VOLKSWAGEN | Owner's Name  | VALVERDE CAR IMPORTS SA DE CV |
| Model  | Atlas             | License Plate | 61 NONE    | Odometer (mi) | 169757 273196.73038 km        |

Monitoring Information and Certificate

|                                |      |                     |      |                |                 |                     |   |                     |
|--------------------------------|------|---------------------|------|----------------|-----------------|---------------------|---|---------------------|
| Misfire Monitor                | PASS | Fuel System Monitor | PASS | Cert Number    | MEN4-00008326   | Geo Location        | Latitude: 31.364765, Longitude: -110.957118 |                     |
| Comprehensive Monitor Catalyst | PASS | O2 Sensor Monitor   | PASS | Inspector Name | 31 Zalma Olmos  | Inspector Signature | <i>Zalma Olmos</i>                          |                     |
| Catalyst Monitor               | PASS | Overall Test Result | PASS | EEI ITN        | X20260526504882 | Date                | 2026/05/29                                  | Expires: 2026/08/29 |



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

