



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5YFBURHE5HP698947		Year	2017	
Mfg In	UNITED STATES	Make	Toyota	Owner's Name	GABRIEL ARMANDO GOMEZ SAMPERIO
Model	Corolla	License Plate	64 NONE	Odometer (mi)	130000 209214.20000 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN4-00009093	Geo Location	Latitude: 31.364765, Longitude: -110.957118	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	31 Zalma Olmos	Inspector Signature	<i>Zalma Olmos</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260514895027	Date	2026/07/15	Expires: 2026/10/15



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

