



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5NPE24AF9JH680494		Year	2018	
Mfg In	UNITED STATES	Make	Hyundai	Owner's Name	VALCA CAR SALES
Model	Sonata	License Plate	61 NONE	Odometer (mi)	101011 162561.04274 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN4-00009832	Geo Location	Latitude: 31.364765, Longitude: -110.957118	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	31 Zalma Olmos	Inspector Signature	<i>Zalma Olmos</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20260821618561	Date	2026/08/28	Expires: 2026/11/28



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

