



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	2G1105SA4G9185914		Year	2016	
Mfg In	CANADA	Make	Chevrolet	Owner's Name	IMPORTADORA DEL SECTOR AUTOMOTRIZ Y MERCANCIAS DEL NOROESTE S DE RL DE C
Model	Impala	License Plate	H4	Odometer (mi)	193909 312065.51006 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN5-00001234	Geo Location	Latitude: 31.364765, Longitude: -110.957118
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	13 Loreto Mendoza	Inspector Signature	Loreto Mendoza
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20250812568827	Date	2025/08/15 Expires: 2025/11/15



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

