



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	1C6JJTEG6ML559637		Year	2021	
Mfg In	UNITED STATES	Make	Jeep	Owner's Name	IMPORTADORA DEL SECTOR AUTOMOTRIZ Y MERCANCIA DEL NOROESTE S DE RL DE CV
Model	Gladiator	License Plate	H2	Odometer (mi)	70216 113001.41744 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN5-00001242	Geo Location	Latitude: 31.364765, Longitude: -110.957118	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	13 Loreto Mendoza	Inspector Signature	Loreto Mendoza	
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20250715090949	Date	2025/08/15	Expires: 2025/11/15



Sernarat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

