



VIN

MECHANICAL EMISSIONS SERVICES LLC
1270 W. Mariposa Ranch Road
Nogales, AZ 85621
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5TDJZRFH6HS398092		Year	2017	
Mfg In	UNITED STATES	Make	Toyota	Owner's Name	IMPORTADORA DEL SECTOR AUTOMOTRIZ Y MERCANCIAS DEL NOROESTE S DE RL DE C
Model	Highlander	License Plate	H4	Odometer (mi)	71991 115857.99594 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEN5-00003238	Geo Location	Latitude: 31.364765, Longitude: -110.957118
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	13 Loreto Mendoza	Inspector Signature	Loreto Mendoza
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20251201713091	Date	2025/12/10 Expires: 2026/03/10



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

