



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3C4NJDCB6KT645796		Year	2019	
Mfg In	MEXICO	Make	Jeep	Owner's Name	ABBY MELISSA PUENTES RODRIGUEZ
Model	Compass	License Plate	K2 NONE	Odometer (mi)	156685 252159.43790 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MER9-00002021	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	09 Ricardo Bucio Jr	Inspector Signature	<i>Ricardo Bucio Jr</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20260827956818	Date	2026/08/28	Expires: 2026/11/28



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

