



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299




Cert Number

Vehicle Information

VIN	3N1AB7AP0KY372372	Year	2019		
Mfg In	MEXICO	Make	Nissan	Owner's Name	ABBY MELISSA PUENTES RODRIGUEZ
Model	Sentra	License Plate	K2 NONE	Odometer (mi)	89782 144489.76388 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MER9-00002024	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	09 Ricardo Bucio Jr	Inspector Signature	<i>Ricardo Bucio Jr</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20260827957995	Date	2026/08/28	Expires: 2026/11/28



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

