



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

| | | | | | |
|--------|-------------------|---------------|---------|---------------|------------------------------------|
| VIN | 3N1AB7APXKY211530 | | Year | 2019 | |
| Mfg In | MEXICO | Make | Nissan | Owner's Name | MULTISERVICIOS LOZAR S DE RL DE CV |
| Model | Sentra | License Plate | K4 NONE | Odometer (mi) | 90554 145732.17436 km |

Monitoring Information and Certificate

| | | | | | | | |
|--------------------------------|------|---------------------|------|----------------|-----------------|---------------------|---|
| Misfire Monitor | PASS | Fuel System Monitor | PASS | Cert Number | MET1-00007011 | Geo Location | Latitude: 31.765747, Longitude: -106.411451 |
| Comprehensive Monitor Catalyst | PASS | O2 Sensor Monitor | PASS | Inspector Name | 03 Sara Corona | Inspector Signature | Sara Corona |
| Catalyst Monitor | PASS | Overall Test Result | PASS | EET ITN | X20250616503140 | Date | 2025/06/17 Expires: 2025/09/17 |



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

