



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3N1AB7AP0HY212727		Year	2017	
Mfg In	MEXICO	Make	Nissan	Owner's Name	MULTISERVICIOS LOZAR S DE RL DE CV
Model	Sentra	License Plate	K4 NONE	Odometer (mi)	103883 167183.06722 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-00007015	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	03 Sara Corona	Inspector Signature	Sara Corona
Catalyst Monitor	PASS	Overall Test Result	PASS	EEL ITN	X20250616505445	Date	2025/06/17 Expires: 2025/09/17



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

