



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299




Cert Number

Vehicle Information

VIN	3CZRU5H50GM735927	Year	2016		
Mfg In	MEXICO	Make	Honda	Owner's Name	AGENCIA ADUANAL INTERNACIONAL DE COMERCIO EXTERIOR LG S DE RL DE CV
Model	HR-V	License Plate	K2 NONE	Odometer (mi)	143701 231263.76734 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-00011278	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	03 Sara Corona	Inspector Signature	<i>Sara Corona</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20251020735927	Date	2025/10/20	Expires: 2026/01/20



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

