



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Vehicle Information

VIN	5LMTJ3DH0HUL04177		Year	2017	
Mfg In	UNITED STATES	Make	Lincoln	Owner's Name	MIGUEL ANGEL LIRA GAYTAN
Model	MKC	License Plate	K4 NONE	Odometer (mi)	108323 174328.53682 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-00011285	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	03 Sara Corona	Inspector Signature	<i>Sara Corona</i>
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20251020004177	Date	2025/10/20 Expires: 2026/01/20



Sernat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

