



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

|        |                   |               |           |               |                        |
|--------|-------------------|---------------|-----------|---------------|------------------------|
| VIN    | 3GNCJKSB3KL138567 |               | Year      | 2019          |                        |
| Mfg In | MEXICO            | Make          | Chevrolet | Owner's Name  | MARISOL AVIÑA HOLGUIN  |
| Model  | Trax              | License Plate | N2 NONE   | Odometer (mi) | 106017 170617.39878 km |

Monitoring Information and Certificate

|                                |      |                     |      |                |                 |                     |   |                     |
|--------------------------------|------|---------------------|------|----------------|-----------------|---------------------|---|---------------------|
| Misfire Monitor                | PASS | Fuel System Monitor | PASS | Cert Number    | MET1-00013935   | Geo Location        | Latitude: 31.765747, Longitude: -106.411451 |                     |
| Comprehensive Monitor Catalyst | PASS | O2 Sensor Monitor   | PASS | Inspector Name | 03 Sara Corona  | Inspector Signature | <i>Sara Corona</i>                          |                     |
| Catalyst Monitor               | PASS | Overall Test Result | PASS | EET ITN        | X20251209138567 | Date                | 2025/12/09                                  | Expires: 2026/03/09 |



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

