



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299




Cert Number

Vehicle Information

| | | | | | |
|--------|-------------------|---------------|------------|---------------|-------------------------|
| VIN | 3VW4T7AJ8HM291376 | | Year | 2017 | |
| Mfg In | MEXICO | Make | Volkswagen | Owner's Name | MONICA GONZALEZ CAZARES |
| Model | Jetta | License Plate | K2 NONE | Odometer (mi) | 147324 237094.40616 km |

Monitoring Information and Certificate

| | | | | | | | | |
|--------------------------------|------|---------------------|------|----------------|-----------------|---------------------|---|---------------------|
| Misfire Monitor | PASS | Fuel System Monitor | PASS | Cert Number | MET1-00020697 | Geo Location | Latitude: 31.765747, Longitude: -106.411451 | |
| Comprehensive Monitor Catalyst | PASS | O2 Sensor Monitor | PASS | Inspector Name | 12 Sara Corona | Inspector Signature | <i>Sara Corona</i> | |
| Catalyst Monitor | PASS | Overall Test Result | PASS | EEI ITN | X20260529291376 | Date | 2026/05/29 | Expires: 2026/08/29 |



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

