



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number



Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	2HGFC1E54HH702441		Year	2017	
Mfg In	CANADA	Make	HONDA	Owner's Name	MONICA GONZALEZ CAZARES
Model	Civic	License Plate	K2 NONE	Odometer (mi)	78137 125748.99958 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-00020699	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Sara Corona	Inspector Signature	Sara Corona	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20260529702441	Date	2026/05/29	Expires: 2026/08/29



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

