



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	2HGFC1F38HH644864		Year	2017	
Mfg In	CANADA	Make	Honda	Owner's Name	MONICA GONZALEZ CAZARES
Model	Civic	License Plate	K2 NONE	Odometer (mi)	187673 302029.66582 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-00020705	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Sara Corona	Inspector Signature	Sara Corona	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20260529644864	Date	2026/05/29	Expires: 2026/08/29



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

