



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5N1AT2MV4JC704727		Year	2018	
Mfg In	UNITED STATES	Make	Nissan	Owner's Name	MONICA GONZALEZ CAZARES
Model	Rogue	License Plate	K2 NONE	Odometer (mi)	152053 244704.97502 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-00020711	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Sara Corona	Inspector Signature	<i>Sara Corona</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20260529704727	Date	2026/05/29	Expires: 2026/08/29



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

