



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299




Cert Number

Vehicle Information

VIN	3GCEC13J48G206033		Year	2008	
Mfg In	MEXICO	Make	Chevrolet	Owner's Name	LUIS ALBERTO GALVAN CERDA
Model	Silverado 1500	License Plate	K2 NONE	Odometer (mi)	163032 262373.91888 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET2-00005150	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	39 Ricardo Rodriguez	Inspector Signature	<i>Ricardo Rodriguez</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20250617206033	Date	2025/06/17	Expires: 2025/09/17



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

