



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3GKALPEX4KL379539		Year	2019	
Mfg In	MEXICO	Make	GMC	Owner's Name	ALEJANDRA YARELI CANO IBARRA
Model	Terrain	License Plate	K4 NONE	Odometer (mi)	45545 73297.39030 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET2-00005154	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	39 Ricardo Rodriguez	Inspector Signature	Ricardo Rodriguez
Catalyst Monitor	PASS	Overall Test Result	PASS	EEL ITN	X20250617379539	Date	2025/06/17 Expires: 2025/09/17



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

