



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5TFAZ5CN0HX051838		Year	2017	
Mfg In	UNITED STATES	Make	Toyota	Owner's Name	JOSE LUIS MEDINA CARRILLO
Model	Tacoma	License Plate	K4 NONE	Odometer (mi)	18624 29972.34816 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET2-00010398	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	39 Ricardo Rodriguez	Inspector Signature	Ricardo Rodriguez
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20251020051838	Date	2025/10/20 Expires: 2026/01/20



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

