



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	1N4AA6AP8HC446557		Year	2017	
Mfg In	UNITED STATES	Make	Nissan	Owner's Name	MIGUEL ANGEL LIRA GAYTAN
Model	Maxima	License Plate	K4 NONE	Odometer (mi)	107635 173221.31090 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET2-00010416	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	39 Ricardo Rodriguez	Inspector Signature	Ricardo Rodriguez
Catalyst Monitor	PASS	Overall Test Result	PASS	EEL ITN	X20251020446557	Date	2025/10/20 Expires: 2026/01/20



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

