



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3FADP4AJ2KM130010		Year	2019	
Mfg In	MEXICO	Make	Ford	Owner's Name	JOSE LUIS MEDINA CARRILLO
Model	Fiesta	License Plate	K2 NONE	Odometer (mi)	88448 142342.90432 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET2-00012516	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	39 Ricardo Rodriguez	Inspector Signature	Ricardo Rodriguez	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20251208130010	Date	2025/12/09	Expires: 2026/03/09



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

