



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299




Cert Number

Vehicle Information

VIN	3N1CN7AP6GL805603		Year	2016	
Mfg In	MEXICO	Make	Nissan	Owner's Name	JOSE LUIS MEDINA CARRILLO
Model	Versa	License Plate	K2 NONE	Odometer (mi)	124456 200292.01904 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET2-00012517	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	39 Ricardo Rodriguez	Inspector Signature	<i>Ricardo Rodriguez</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20251208805603	Date	2025/12/09	Expires: 2026/03/09



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

