



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

| | | | | | |
|--------|-------------------|---------------|---------|---------------|--------------------------|
| VIN | 3N1AB8CV5MY318439 | | Year | 2021 | |
| Mfg In | MEXICO | Make | Nissan | Owner's Name | MIGUEL ANGEL LIRA GAYTAN |
| Model | Sentra | License Plate | 94 NONE | Odometer (mi) | 75030 120748.78020 km |

Monitoring Information and Certificate

| | | | | | | | |
|--------------------------------|------|---------------------|------|----------------|----------------------|---------------------|---|
| Misfire Monitor | PASS | Fuel System Monitor | PASS | Cert Number | MET2-00012686 | Geo Location | Latitude: 31.765747, Longitude: -106.411451 |
| Comprehensive Monitor Catalyst | PASS | O2 Sensor Monitor | PASS | Inspector Name | 39 Ricardo Rodriguez | Inspector Signature | Ricardo Rodriguez |
| Catalyst Monitor | PASS | Overall Test Result | PASS | EET ITN | X20251210267778 | Date | 2025/12/10 Expires: 2026/03/10 |



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

