



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	1N4AA6AP3HC373758		Year	2017	
Mfg In	UNITED STATES	Make	Nissan	Owner's Name	MARISOL AVIÑA HOLGUIN
Model	Maxima	License Plate	N4 NONE	Odometer (mi)	161055 259192.25370 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET2-00012695	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	39 Ricardo Rodriguez	Inspector Signature	Ricardo Rodriguez
Catalyst Monitor	PASS	Overall Test Result	PASS	EEL ITN	X20251209373758	Date	2025/12/10 Expires: 2026/03/10



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

