



VIN

MECHANICAL EMISSIONS SERVICES LLC
8710 Siempre Viva RD
San Diego, CA 92154
(619) 845-1299



Cert Number

Vehicle Information

VIN	3VV2B7AX5JM154498		Year	2018		
Mfg In	MEXICO	Make	Volkswagen	Owner's Name	VEHICULOS BAJA MAX	
Model	Tiguan	License Plate	J2 NONE	Odometer (mi)	194325	312734.99550 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET2-00023892	Geo Location	Latitude: 32.553688, Longitude: -116.956459	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	39 Ricardo Rodriguez	Inspector Signature	<i>Ricardo Rodriguez</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20260821600727	Date	2026/08/28	Expires: 2026/11/28



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

