



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3GTU2PEJXHG152865	Year	2017		
Mfg In	MEXICO	Make	GMC	Owner's Name	MONICA GONZALEZ CAZARES
Model	Sierra K1500	License Plate	K2 NONE	Odometer (mi)	130245 209608.48830 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET4-00001114	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	08 Alejandra Hernandez	Inspector Signature	Alejandra Hernandez	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20260529152865	Date	2026/05/29	Expires: 2026/08/29



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

