



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number



Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3GCUKSEJXH40937		Year	2017	
Mfg In	MEXICO	Make	CHEVROLET	Owner's Name	JANETTE ALVIDREZ MERAZ
Model	Silverado	License Plate	K4 NONE	Odometer (mi)	128480 206768.00320 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET4-00003791	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	08 Alejandra Hernandez	Inspector Signature	Alejandra Hernandez
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260715440937	Date	2026/07/15 Expires: 2026/10/15



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

