



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3N1CN7AP6HL834262		Year	2017	
Mfg In	MEXICO	Make	Nissan	Owner's Name	MIGUEL ANGEL LIRA GAYTAN
Model	Versa	License Plate	K4 NONE	Odometer (mi)	93564 150576.28776 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET5-00001286	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	20 Saul Corona	Inspector Signature	Saul Corona
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20241226834262	Date	2024/12/26 Expires: 2025/03/26



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

