



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299




Cert Number

Vehicle Information

VIN	7FARW2H5XJE096132		Year	2018	
Mfg In	UNITED STATES	Make	Honda	Owner's Name	JOSE LUIS MEDINA CARRILLO
Model	CR-V	License Plate	K2 NONE	Odometer (mi)	100361 161514.97174 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET5-00010991	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	20 Saul Corona	Inspector Signature	<i>Saul Corona</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20251209096132	Date	2025/12/09	Expires: 2026/03/09



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

