



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5NPEG4JA3MH105821		Year	2021	
Mfg In	UNITED STATES	Make	Hyundai	Owner's Name	JOSE EDUARDO GONZALEZ CHAVEZ
Model	Sonata	License Plate	K2 NONE	Odometer (mi)	105832 170319.67088 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET5-00010999	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	20 Saul Corona	Inspector Signature	<i>Saul Corona</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20251209105821	Date	2025/12/09	Expires: 2026/03/09



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

