



VIN

**MECHANICAL EMISSIONS SERVICES LLC**  
**6225B Alameda Avenue**  
**El Paso, TX 79905**  
**(619) 845-1299**



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3GCUKTEJ8JG161269		Year	2018	
Mfg In	MEXICO	Make	Chevrolet	Owner's Name	JOSE LUIS MEDINA CARRILLO
Model	Silverado 1500	License Plate	K4 NONE	Odometer (mi)	151357 243584.87438 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET5-00011139	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	20 Saul Corona	Inspector Signature	<i>Saul Corona</i>
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20251210161269	Date	2025/12/10 Expires: 2026/03/10



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

