



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5TFSZ5AN5HX077438		Year	2017	
Mfg In	UNITED STATES	Make	Toyota	Owner's Name	JOSE LUIS MEDINA CARRILLO
Model	Tacoma	License Plate	K4 NONE	Odometer (mi)	148795 239461.74530 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET5-00012508	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	20 Saul Corona	Inspector Signature	<i>Saul Corona</i>
Catalyst Monitor	PASS	Overall Test Result	PASS	EEL ITN	X20260123077438	Date	2026/01/23 Expires: 2026/04/23



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

